

REVISION INSTRUCTION SHEET

**33201 Piston Engine Constant Speed
Propeller Governors**

**Revision 1 - 2007
Cover Page, Manual 33201**

Remove

Cover page dated Revision 2-2001

List of Effective Chapter Dates Revision 2-2001

Insert

Cover page dated Revision 1-2007

List of Effective Chapter Dates Revision 1-2007

REVISION INSTRUCTION SHEET



AIRCRAFT CONTROLS GROUP

SPECIFICATION MANUAL 33201

FOR

***PISTON ENGINE
CONSTANT SPEED
PROPELLER GOVERNORS***

REVISION 1-2007

WOODWARD GOVERNOR COMPANY
ONE WOODWARD WAY
P.O. BOX 405
ROCKTON, IL 61072-0405, USA

In addition to this manual and subsequent revisions, additional overhaul and repair information is published in the form of Service Bulletins and Temporary Revisions. The information contained in these documents form an integral part of the maintenance data and are to be used in conjunction with the information contained in this Specification Manual.

MANUAL NO. 33201

**33201 Piston Engine Constant Speed
Propeller Governors**

Revision 1-2007

List of Effective Chapter Dates, Manual 33201

CHAPTER	LATEST REVISION
Cover Page	Revision 1-2007
I. Assembly Drawings	Revision 2-2001
II. Governor Common Parts	New Edition-1984
III. Governor Spring Marking	Revision 2-1998
IV. Governor Sub-Assemblies	Revision 1-2001
V. Rework Drawings	Revision 1-1996
VI. Hydraulic Accumulators	N/A
VII. Test Specifications	Revision 1-1997
VIII. Governor Installation Instructions	Revision 1-1994
IX. Governor Engineering Change Histories	Revision 2-2001
Volume III LOEP	Revision 1-2007

REVISION INSTRUCTION SHEET

**33201 Piston Engine Constant Speed
Propeller Governors**

**Revision 1-2007
Volume 3
Operation-Maintenance Manuals and
Service Bulletins List of Effective Pages**

Remove

List of Effective Pages dated Revision 1-2001

Insert

List of Effective Pages dated Revision 1-2007

REVISION INSTRUCTION SHEET

NOTE: This table lists the latest revisions of manuals and service bulletins contained in Specification Manual 33201, and only these versions should be used for repair and overhaul. Use this table to verify you are using the latest revision.

<u>GOVERNOR MANUALS</u>	<u>TITLE</u>
33001B Oct. 71	CSSA PROPELLER GOVERNOR
33002B Jan. 82	CSSA PROPELLER GOVERNOR 3/8" PILOT VALVE
33017D Nov. 78	BALANCED PILOT VALVE GOVERNOR
33092A Rev. 2, Jun 7/96	ADJUSTABLE HEAD TYPE
33169 Jan. 86	GOVERNOR PULLEY HEAD
33194 Dec. 88	NEW ADJUSTABLE HEAD TYPE
<u>SERVICE BULLETINS</u>	<u>TITLE</u>
33502B	BEARING INSERTION TOOL
33514A	LOOSE BY-PASS PLUGS
33519	210060 GOVERNOR USED ON BEECH MENTOR AIRCRAFT
33520	RELIEF VALVE SPRING AND ASSEMBLY
33522	INSTALLATION OF FLYWEIGHT RETAINING RING
33524A	SHORT OIL CONTROL PLUG
33526	RETAINING RING MODIFICATION TO WIDER RING
33527	SPEEDER SPRING RETENTION
33529A	DRIVE GEAR P/N 210206
33530	REVISED GOVERNOR TEST SPECIFICATIONS
33531C	SAFETY CRITICAL PARTS INSPECTION & SPLINE WEAR
33534A	LOOSE SPEED ADJUSTING LEVERS
33535	SPEED ADJUSTMENT LEVERS AND SHAFT REPLACEMENT
33537A	SPEED ADJUSTMENT LEVERS
33538	DRIVE GEAR REPLACEMENT ON BRITTEN-NORMAN
33539C	TEST-BRITTEN NORMAN AIRCRAFT
33539C SUPP. #1	SERVICE LIFE CONTROL OF DRIVE GEAR
33540	NEW THRUST BEARING FOR SOME GOVERNORS
33542	CAM TYPE PULLEY HEAD
33543	NEW FLYWEIGHT ASSEMBLIES
33544	RELIEF VALVE SLEEVE-RECIPROCATING ENGINES CUP TYPE FLYWEIGHT HEAD USED IN EARLY 210XXX TYPE PROP GOVERNORS
33546	SPEED ADJUSTMENT SHAFT, LEVER CLAMP, AND LEVER SCREW REPLACEMENT
33549	UNFEATHERING FUNCTIONS INSPECTION
33551B	REPLACEMENT OF SYNCHRONIZER PULLEY INSTALLED ON SLAVE PROPELLER GOVERNOR
33555B	TIGHT SPEED ADJUSTMENT SHAFTS
33556B	NEW SPEED ADJUSTMENT SHAFTS AND PARTS CHANGE ON SOME FEATHERING TYPE PROPELLER GOVERNORS
33558	ADJUSTMENT COVER CLAMP ON ADJUSTABLE HEAD GOVERNORS
33560	GOVERNORS
33562	BEARING RACES, TYPE II SYNCHRONIZER

NOTE: This table lists the latest revisions of manuals and service bulletins contained in Specification Manual 33201, and only these versions should be used for repair and overhaul. Use this table to verify you are using the latest revision.	
33564	1/4" PILOT VALVE INFORMATION
<u>SERVICE BULLETINS</u>	<u>TITLE</u>
33570A	USE OF WOODWARD OVERHAUL KITS
33571C	TUBULAR PILOT VALVE INSPECTION AT OVERHAUL ADDITION OF SPACER WASHERS TO OFFSET TOE TYPE FLYWEIGHT HEADS USED ON RECIPROCATING ENGINE
33572A	GOVERNORS
33574B	SUDDEN STOPPAGE, CONTAMINATION, LIGHTNING STRIKE
33576	RECALL OF WOODWARD F210681 PROPELLER GOVERNORS
33578	RIGGING OF SLAVE ENGINE PROP CONTROL LEVER
33580M	RECOMMENDED TBO FOR WOODWARD PROPELLER GOVERNORS UNFEATHERING CHECK VALVE CALIBRATION ON
33581	P/N L210652 AND R210652
33585	POSSIBLE CONTAMINATION OF WOODWARD PROPELLER GOVERNORS DURING SHIPMENT

REVISION INSTRUCTION SHEET

**33201 Piston Engine Constant Speed
Propeller Governors**

**Revision 1-2007
Volume 3
Operation-Maintenance Manuals and
Service Bulletins**

Remove

33580J

Insert

33580M

REVISION INSTRUCTION SHEET